



DE ANLEITUNG GEWEBE REPARATURSET FÜR GEObox

EN Instruction repair set for GEObox fabric

SICHERHEITSHINWEISE

- Im Aufstellungsraum dürfen keine spitzen oder scharfen Gegenstände vorhanden sein, da es bei Berührung zu Beschädigungen des Gewebes kommen kann.
- Das Gewebe muss vor Sonneneinstrahlung geschützt werden (gilt auch für Reparaturset)
- Bei jeglichen Arbeiten an der Pelletbox muss diese stromfrei geschaltet werden (Heizung abschalten, System vom Netz trennen...)
- Bei der Montage des Reparatursets darf die Pelletbox nicht durch Personen bestiegen werden! Eine separate Aufstiegshilfe (z.B. Stehleiter) ist bei Bedarf zu verwenden.
- Bei der Montage des Reparatursets und generell bei jeglichen Arbeiten an der Pelletbox und am Austragungssystem muss geeignete Sicherheitsbekleidung (Handschuhe...) verwendet werden!

SAFETY INSTRUCTIONS

- No sharp items are allowed in the room of installation, as any contact with sharp items may damage the fabric.
- The fabric must be protected from sunlight.
- For all works on the pelletbox electricity must be switched off (power off heating system, separate system from power supply...)
- Both during mounting and operation climbing on the pelletbox is prohibited. A separate climbing aid (e.g. step ladder) should be used when needed.
- Appropriate protective clothing and equipment has to be worn (i.e. gloves...) during installation of the storage system and during any operation on storage system or the extraction unit.

ALLGEMEINES, MONTAGE

- Positionierungsmöglichkeiten: grundsätzlich an der Decke des Pelletsilos - je nach Einriss des Gewebes auch seitlich (Montage von innen, Abklärung durch Hersteller erforderlich!)
- überklebbarer Bereich bzw. maximale Risslänge des Gewebes: ca. 20cm
- Klebestelle muss staubfrei sein
- Schutzfolie abziehen, Reparaturset aufkleben und kurzzeitig fest andrücken

GENERAL INFORMATION, MOUNTING

- Mounting possibilities: basically on the upper part of the silo – depending on the crack of the fabric also sidelong (mounting from the inside, on consultation with the producer!)
- Bonding area or maximum crack length of the fabric: about 20 cm
- Bonding area must be dust-free
- Remove protective foil, stick repairing set and press briefly

